



Welkom

**BREDA-
DATA**

Panel

Introductie



BREDA_

Smart City.





Gemeente Breda

TOEKOMSTPERSPECTIEF
OPENBARE
RUIJITE

PROSPECT LAB 1

DE SLIMME STAD

Data & Digitalisering | Organiseren
Het systeem | Inrichting | Sociaal

PROSPECT LAB 2

DE VERDICHTENDE STAD

Mobiliteit | Organiseren | Inrichting | Bewoners
Gebruik | Beheer, onderhoud & ontwikkelen
Bekostiging

PROSPECT LAB 3

ANDER GEBRUIK

Mobiliteit | Wonen | Bewoners | Bezoekers
Bedrijven | Binnenstad | Beleid | Functies

PROSPECT LAB 4

DE VERANDERENDE STAD


Klimaat | Energie-transitie | Participatie
Deeleconomie | Ruimtelijke ordening | Ondergrond
Beleid | Beheer & ontwerp | Bekostiging

Beleid | Beheer & ontwerp | Bekostiging
Deeleconomie | Ruimtelijke ordening | Ondergrond
Klimaat | Energie-transitie | Participatie

DE VERANDERENDE STAD

***“It’s not the strongest
of species that survives,
nor the most intelligent,
but the one most
responsive to change.”***

Charles Darwin




**BREDA-
DATA**

Digitale Transformatie




BREDA



Praktijkvoorbeeld

INSPECH



INSPECH



Jasper Wognum
Brain Creators

rtlnews

INSPECH

INSPECH

Glenn

Breda Complete

Section ID

Neighborhood/District

Condition

- Direct <1y
- Short 1y-2y
- Medium 2y-5y
- Long 5y+

Distresses

- Raveling
- Alligator cracking
- Transverse crack
- Longitudinal crack
- Pothole
- Bleeding
- Patching
- Marking damage
- Mechanical damage
- Transverse joint
- Longitudinal joint

Layers

- Distresses
- Sections
- Road Images
- Work Orders
- Repaired Distresses

Repaired Distresses

Work Orders

Road Images

Sections

Distresses

INSPECH

INSPECH

Editing Mode

Distress: Ravelling
Type: E
Coordinates: 5182417N, 444324E
Image: hanna_gentil...
Created: 1 year ago
Updated: 1 year ago
[Mark as reported](#)

Section Information

Work Order 1171

Status: Created
Asset: Workorder for 23354
Asset type: 1
Job plan ID: J10018
Job Measure: GGG + conserven
Work Order ID: 1171
Work description: GGG + conserven - WJ 26 - Phase 4 on W Stage 10's oppervlak + oppervlakteron during
Work unit: 1
Unit Cost: 95.73
Total Cost: 95.73
Created: Ecosdrin 1/25/1870
[Approve Work Order](#)
[Cancel Work Order](#)

View on Table

Select Distress Label

- Ravelling
- Aligner cracking
- Transverse crack
- Longitudinal crack
- Pothole
- Spalling
- Fracturing
- Sealing damage
- Mechanical damage
- Transverse joint
- Longitudinal joint

- challenge box
- parameter box
- parameter details
- parameter details
- parameter
- parameter
- parameter
- challenge box
- parameter box
- parameter details
- parameter details

INSPECH

INSPECH

Breda Complete

Section ID

Neighborhood/District

Condition

- Direct <1y
- Short 1y-2y
- Medium 2y-5y
- Long 5y+

Distresses

- Raveling
- Alligator cracking
- Transverse crack
- Longitudinal crack
- Pothole
- Bleeding
- Patching
- Marking damage
- Mechanical damage
- Transverse joint
- Longitudinal joint

Layers

- Distresses
- Sections
- Road Images
- Work Orders
- Repaired Distresses

Section: 19670
Short term

Section ID: 19670
Name: N/A
Road Type: N/A
Maintenance: Short term

Raveling

Score: G
Area: N/A
Maintenance: Long term

Cracking

Score: E3
Rel. dist. m: 56.44
Maintenance: Short term

Glenn

- add new distresses
- new areas
- new roads
- new

INSPECH

INSPECH

Breda Complete

Section ID

Neighborhood/District

Condition

- Direct <1y
- Short 1y-2y
- Medium 2y-5y
- Long 5y+

Distresses

- Raveling
- Alligator cracking
- Transverse crack
- Longitudinal crack
- Pothole
- Bleeding
- Patching
- Marking damage
- Mechanical damage
- Transverse joint
- Longitudinal joint

Layers

- Distresses
- Sections
- Road Images
- Work Orders
- Repaired Distresses

Distress
Longitudinal crack F

Distress
Longitudinal crack
Type F
Coordinates 57°29'37"N
4°44'27"E
Image honus_geotiff...
Created 1 year ago
[Mark as repaired](#)

Glenn

- Allowing Distresses
- New Areas
- New Images
- New Work Orders

INSPECH

INSPECH

Breda Complete

Section ID

Neighborhood/District

Condition

- Direct <1y
- Short 1y-2y
- Medium 2y-5y
- Long 5y+

Distresses

- Raveling
- Alligator cracking
- Transverse crack
- Longitudinal crack
- Pothole
- Bleeding
- Patching
- Marking damage
- Mechanical damage
- Transverse joint
- Longitudinal joint

Layers

- Distresses
- Sections
- Road Images
- Work Orders
- Repaired Distresses



Work Order 1187

Status: Completed

Asset description: Workorder for 01873

Asset type: 1

Job plan ID: J10010

Job Measure: GOO + conservaren

Work Order ID: 1187

Work description: GOO + conservaren - 100 200 meters 4 cm + Image 05 oppervlak + oppervlakteplan datering

Work unit: 1

Unit Cost: 95,73

Total Cost: 95,73

Created: Escudrain 1/20/1070

[View on Table](#)

- add new distress
- add new section
- add new work order
- add new layer

INSPECH

